

# INFORMAȚII PRIVIND UTILIZAREA ÎN SIGURANȚĂ A SVHC-URILOR

INFORMAȚII DIN ARTICOLUL 33 DIN REACH CU PRIVIRE LA SUBSTANȚELE CARE PREZINTĂ MOTIVE DE ÎNGRIJORARE DEOSEBITĂ (SVHC)

Stimate client,

Articolul 33 alineatul (1) din Regulamentul REACH (Reg. CE 1907/2006) vizează să permită clienților să ia orice măsuri relevante de management al riscului, care pot decurge din prezența în articole a substanțelor care prezintă motive de îngrijorare deosebită (SVHC), prezente în actuala listă de candidați la autorizare, pentru a garanta utilizarea lor în siguranță.

FORD susține obiectivele subiacente ale REACH, în general, și ale articolului 33 alineatul (1) în special, care sunt în concordanță cu propriul nostru angajament de a promova fabricarea, manipularea și utilizarea responsabilă a produselor noastre.

## Identificarea SVHC-urilor

Din câte știm, pe baza informațiilor provenite din lanțul nostru de aprovizionare și din propriile noastre date privind produsele, SVHC-urile prezente în articolele componente într-o concentrație mai mare de 0,1 % sunt cele prezentate în „Lista SVHC-urilor” relevantă pentru vehiculul/piesa specifică.

## Informații speciale privind utilizarea în siguranță pentru articolele care conțin SVHC-uri

Dacă este cazul, informațiile speciale privind utilizarea în siguranță pentru articolele care conțin SVHC-uri sunt adăugate la „Lista SVHC-urilor” relevantă pentru vehiculul/piesa specifică.

## Informații generale privind utilizarea în siguranță pentru articole

Fiecare vehicul FORD este dotat cu un manual al proprietarului, care include informații privind utilizarea în siguranță pentru proprietarii/operatorii vehiculului. Informațiile FORD cu privire la efectuarea lucrărilor de reparare și întreținere și la piesele originale includ, de asemenea, și informații privind utilizarea în siguranță a acestora pentru personalul care asigură service-ul.

Când sunt prezente în piesele acestui vehicul, SVHC-urile prezentate în „Lista SVHC-urilor” pentru vehiculul/piesa specifică sunt integrate în așa fel încât potențiala expunere a clienților este redusă la minim, iar pericolele pentru om sau mediu pot fi excluse atât timp cât vehiculul și piesele acestuia sunt utilizate așa cum au fost menite și orice lucrări de reparare, service și întreținere sunt realizate urmând instrucțiunile tehnice pentru activitățile respective și bunele practici standard ale industriei.

Un vehicul aflat la sfârșitul duratei de viață poate fi eliminat în mod legal, în Uniunea Europeană, doar la o instalație de tratare autorizată (ITA). Piesele vehiculelor trebuie să fie eliminate în conformitate cu legile locale aplicabile și sub îndrumarea autorităților locale.

## Model: Ford Puma

Lista SVHC-urilor bazată pe lista de candidați ECHA, începând din 1 iulie 2022

Informații speciale privind utilizarea în siguranță pentru articolele care conțin SVHC-uri

Nu sunt necesare niciun fel de informații speciale pentru utilizarea în siguranță - vă rugăm să respectați informațiile generale privind utilizarea în siguranță pentru articole.

Commodity	REACH SVHCs
A/C Compressor	Lead[7439-92-1]
A/C Lines, Receiver Drier and Accumulator	Lead[7439-92-1]
ABS/ESC Module	Lead[7439-92-1]
Accessories	1,2-Dimethoxyethane[110-71-4] C,C'-azodi(formamide)[123-77-3] Lead[7439-92-1]
Active and Air Suspension	Lead[7439-92-1]
Adaptive Cruise Control	Lead[7439-92-1]
Air Brakes	Lead[7439-92-1]
AIS - Air Cleaner and Low Pressure Ducts	Lead[7439-92-1]
AIS - High Pressure Ducts	Lead[7439-92-1]
Alternator	Lead[7439-92-1]
Antenna	Lead[7439-92-1]
Battery	Lead[7439-92-1]
Body Structure - Floor Pan - Front Floor and Side Sill	Diboron-trioxide[1303-86-2] Lead[7439-92-1] Refractory ceramic fibres[142844-00-6]
Body Structure - Floor Pan - Rear Floor	Lead[7439-92-1]
Body Structure - Hood Assembly (incl Hinge/Supt)	2-(2H-Benzotriazol-2-yl)-4,6-ditertpentylphenol[25973-55-1]
Brake - Parking	2-(2H-Benzotriazol-2-yl)-4,6-ditertpentylphenol[25973-55-1] Lead[7439-92-1] Methyloxirane[75-56-9]
Brake Actuation	Lead[7439-92-1]
Brake Tubes and Hoses	Lead[7439-92-1]
Brakes - Caliper & Anchor Brkt Assy (Front, Rear)	Lead[7439-92-1]
Brakes - Drum (Front/Rear)	Lead[7439-92-1]

<b>Bumpers Beams (Un-Exposed) - Front/Rear</b>	Lead[7439-92-1]
<b>CHMSL</b>	Lead[7439-92-1]
<b>Clutch / DMF (Dual Mass Flywheel)</b>	Lead[7439-92-1]
<b>Consumer Electronics Interface Module</b>	Lead[7439-92-1]
<b>Control Arm and Bushing Assembly</b>	Imidazolidine-2-thione[96-45-7]
<b>Cooling Fans</b>	Lead[7439-92-1]
<b>Cooling Hoses &amp; Bottles</b>	Lead[7439-92-1]
<b>EDS Wiring Assembly &amp; Components</b>	Lead[7439-92-1]
<b>Electro/Mechanical Devices</b>	Lead[7439-92-1]
<b>Electronic Control Panel and CCH</b>	Lead[7439-92-1]
	N,N-Dimethylacetamide[127-19-5]
	Octamethylcyclotetrasiloxane[556-67-2]
<b>Electronic Modules - Amplifiers</b>	1,6,7,8,9,14,15,16,17,17,18,18-Dodecachloropentacyclo[12.2.1.16,9.02,13.05,10]octadeca-7,15-diene[13560-89-9]
<b>Electronic Modules - Displays</b>	2-(2H-Benzotriazol-2-yl)-4,6-ditertpentylphenol[25973-55-1]
	Lead[7439-92-1]
<b>Electronic Modules - Door Zone</b>	Lead[7439-92-1]
<b>Electronic Modules - Headlamp</b>	Lead[7439-92-1]
<b>Electronic Modules - Power Decklid/Liftgate (PLG)</b>	Lead[7439-92-1]
<b>Electronic Modules - SYNC</b>	2-Methylimidazole[693-98-1]
	Lead[7439-92-1]
<b>Engine Sealing (Including head gaskets)</b>	Lead[7439-92-1]
<b>Evaporator and Blower Assemby (HVAC Module)</b>	Lead[7439-92-1]
<b>Exhaust Cold End (Muffler &amp; Output Pipe Assembly)</b>	Lead[7439-92-1]
<b>FEAD</b>	Lead[7439-92-1]
<b>First Row Door Window Lift Assy</b>	Lead[7439-92-1]
<b>Front Seat Frames</b>	Lead[7439-92-1]
<b>Front Seat Trim Set</b>	Lead[7439-92-1]
<b>Fuel Canister Assembly</b>	Lead[7439-92-1]
<b>Fuel Lines</b>	Lead[7439-92-1]
<b>Fuel Tanks</b>	Lead[7439-92-1]
<b>Half Shaft(s)</b>	Lead[7439-92-1]
	Sodium borate, decahydrate[1303-96-4]
<b>Headlamp / Side Marker</b>	Lead[7439-92-1]
<b>Headliner / Sunvisor</b>	C,C'-azodi(formamide)[123-77-3]
<b>I/S Mirror</b>	Lead[7439-92-1]
<b>Instrument Cluster</b>	Lead[7439-92-1]
<b>Interior Lighting</b>	1,2-Dimethoxyethane[110-71-4]
	4,4'-Isopropylidenediphenol[80-05-7]
	Lead[7439-92-1]
<b>Latches - Hood, Decklid and Liftgate Latches</b>	Lead[7439-92-1]
<b>Latches - Side Door/Latch Mini Module</b>	6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol[119-47-1]

	Lead[7439-92-1]
<b>Locks</b>	Lead[7439-92-1]
<b>Mirrors</b>	Lead[7439-92-1]
<b>Moonroof</b>	Lead[7439-92-1]
<b>Overhead Console</b>	Lead[7439-92-1]
<b>Paint</b>	2-(2H-Benzotriazol-2-yl)-4,6-ditertpentylphenol[25973-55-1]
<b>Park Assist</b>	Lead[7439-92-1]
<b>PATS Transceiver</b>	Lead[7439-92-1]
<b>PCV System</b>	Imidazolidine-2-thione[96-45-7]
<b>Pedal Box</b>	6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol[119-47-1]
<b>Plastic Bumpers and Fascias</b>	Lead[7439-92-1]
<b>PT Mounts</b>	Lead[7439-92-1]
<b>PT Sensors</b>	Lead[7439-92-1]
<b>Rain and Daylight Sensor</b>	1,3,5-Tris(oxiranylmethyl)-1,3,5-triazine-2,4,6(1H,3H,5H)-trione[2451-62-9]
<b>Rear Closure Support &amp; Checks</b>	Lead[7439-92-1]
<b>Rear Floor</b>	Dicyclohexyl-phthalate[84-61-7]
	Lead[7439-92-1]
<b>Restraint Electronics</b>	Lead[7439-92-1]
<b>Seat Belt Assembly Front Row</b>	Disodium-octaborate[12008-41-2]
	Lead[7439-92-1]
<b>Seat Belts - Second Row</b>	Disodium-octaborate[12008-41-2]
<b>Seats - Foam - Cut and Sew</b>	C,C'-azodi(formamide)[123-77-3]
<b>Seats - JIT</b>	Lead[7439-92-1]
<b>Seats - Structures</b>	Lead[7439-92-1]
<b>Second Row Door, Qtr &amp; Rear Closure Window Lift Assy</b>	Lead[7439-92-1]
<b>Second Row Seat Trim Set</b>	C,C'-azodi(formamide)[123-77-3]
<b>Second Row Type Bench or Split Seat Frames</b>	1-Methyl-2-pyrrolidone[872-50-4]
<b>Shifter Cables/Brackets - Auto</b>	1-Methyl-2-pyrrolidone[872-50-4]
	C,C'-azodi(formamide)[123-77-3]
	Lead[7439-92-1]
<b>Side and Rear Vision (BLIS)</b>	Dodecamethylcyclohexasiloxane[540-97-6]
<b>Smart Data Link Module</b>	Lead[7439-92-1]
<b>Speakers / Tweeters</b>	N,N-Dimethylacetamide[127-19-5]
<b>Static Sealing</b>	C,C'-azodi(formamide)[123-77-3]
	Dicyclohexyl-phthalate[84-61-7]
<b>Steering Column</b>	Lead[7439-92-1]
<b>Steering Gear and Linkage</b>	Imidazolidine-2-thione[96-45-7]
	Lead[7439-92-1]
<b>Steering Wheel, Drive Air Bag</b>	Alkanes, C14-17, chloro[85535-85-9]
	Dicyclohexyl-phthalate[84-61-7]
	Lead[7439-92-1]
<b>Suspension Link Components</b>	Lead[7439-92-1]
<b>Switches - General Use</b>	2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one[71868-10-5]
	Lead[7439-92-1]
<b>Switches - Headlamp. Window &amp; Door</b>	2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one[71868-10-5]
	4,4'-Isopropylidenediphenol[80-05-7]
	Lead[7439-92-1]
<b>Switches - Steering Column</b>	4,4'-Isopropylidenediphenol[80-05-7]
<b>Taillamp / Redundant</b>	2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one[71868-10-5]

	Lead[7439-92-1]
<b>Temperature Sensors - Climate</b>	1,3,5-Tris(oxiranylmethyl)-1,3,5-triazine-2,4,6(1H,3H,5H)-trione[2451-62-9]
	2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one[71868-10-5]
	Lead[7439-92-1]
<b>Tires</b>	Lead[7439-92-1]
<b>TMK and Tools</b>	Lead[7439-92-1]
<b>TPMS</b>	Lead[7439-92-1]
<b>Transmission - Auto</b>	Imidazolidine-2-thione[96-45-7]
	Lead[7439-92-1]
<b>Transmission - Manual</b>	Lead[7439-92-1]
<b>Wiper Assembly (Rear, Front) &amp; Washer System</b>	Imidazolidine-2-thione[96-45-7]
	Lead[7439-92-1]
<b>xEV - DCDC</b>	Lead[7439-92-1]
<b>xEV - Traction Battery (as Shipped)</b>	2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one[71868-10-5]